

Oil Field Environmental Incident Summary

Incident: 20140114133853 **Date/Time of Notice:** 01/14/2014 13:27

Responsible Party: Wind River Oil Service

Well Operator: STATOIL OIL & GAS LP

Well Name: ALEXANDER SWD 1

Field Name: LONESOME

Well File #: 90173

Date Incident: 1/14/2014 **Time Incident:** 0954

Facility ID Number:

County: MCKENZIE

Twp: 151

Rng: 102

Sec: 13

Qtr: SE SE

Location Description:

Submitted By: Grady Holt

Received By:

Contact Person: Grady Holt
6300 BRIDGE POINT PKY, BLDG 2
SUITE 500
AUSTIN, TX 78730

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building: 0.5 Miles

Distance Nearest Water Well: 0.5 Miles

Type of Incident: Tank Leak

Release Contained in Dike: Yes - On Facility Site

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil	0	barrels	0	barrels		
Brine	2	barrels	2	barrels		
Other	0	barrels	0	barrels		

Description of Other Released Contaminant:

Inspected:

Written Report Received:

Clean Up Concluded:

Risk Evaluation:

none

Areal Extent:

Potential Environmental Impacts:

none

Action Taken or Planned:

Preventive checks and measures while doing pre-trip inspection to include tank hatches.

Wastes Disposal Location: Prairie Soild Waste Disposal, Newalta Soild Waste Disposal

Agencies Involved:

Updates

Date: 1/14/2014 **Status:** Reviewed - Assigned to Other Agency

Author: Roberts, Kris

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release was contained on location, within the diking, according to the report. NDIC retains oversight.